

TASK: The following passage describes a fatal ground collision which happened in Madrid in 1983. Complete the gaps with the words given below.

attempted / conditions / scheduled / inadequate / investigators / registered /
accidentally / clearance / operating / rolled / rotating / end / lift-off / markings /
fog / fire / bound / cleared / rear / visibility / path

On 7 December 1983, a Boeing 727 of Iberia (Spain's state airline) 1) _____ *EC-CFJ*, operating Iberia Flight 350, a 2) _____ flight to Rome's Leonardo da Vinci–Fiumicino Airport, was 3) _____ for take-off from Madrid-Barajas Airport's Runway 01 in 4) _____ of thick fog. At the same time, a DC-9 of Aviaco registered *EC-CGS*, 5) _____ Aviaco Flight 134, was taxiing to the 6) _____ of the same runway for take-off 7) _____ for Santander Airport. As the Boeing 727 8) _____ along the runway, the crew of the DC-9 9) _____ made a wrong turn in the 10) _____ and taxied their aircraft onto the runway, into the 11) _____ of the 727. The crew of the 727 saw the DC-9 and 12) _____ to avoid the collision by 13) _____ their aircraft for 14) _____, however the 727 had not reached flying speed and its 15) _____ fuselage struck the DC-9. Both aircraft caught 16) _____ and were destroyed; all 42 people on board the DC-9 were killed, while 51 (50 passengers, one crew member) of the 93 on board the Boeing 727 were killed. 17) _____ found that the Boeing 727 and DC-9 had collided due to the poor 18) _____ at the airport, as well as 19) _____ signs and 20) _____, which led to the DC-9 entering the runway without 21) _____ as the Boeing 727 was taking off.